



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

L.J. Olivier
Vice President Nuclear and Station Director

December 15, 1997
BECo Ltr. 2.97.131

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed supplemental Licensee Event Report (LER) 97-014-01, "Transmitters Not Calibrated in Accordance with the Technical Specifications", is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitment:

Procedure 1.8, "Master Surveillance Tracking Program," will be revised to enhance the interval codes, definitions, field categories, and details of responsibility.

Please do not hesitate to contact me if there are any questions regarding this report.

L.J. Olivier
for L. J. Olivier

RLC/dmc/9701401

Enclosure: LER 97-014-01

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Alleandale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

9712230099 971215
PDR ADOCK 05000293
S DR

JE22/1

