

ENCLOSURE 2

NOTICE OF DEVIATION

Florida Power Corporation  
Crystal River Unit 3

Docket No. 50-302  
License No. DPR-72

The following deviation was identified during an inspection conducted on March 8 - April 11, 1986:

In a letter to the Nuclear Regulatory Commission from Florida Power Corporation dated December 19, 1985, the licensee identified a design error that could result in a loss of the Nuclear Services Seawater and the Decay Heat Seawater pumps in the event of a fire. In the corrective actions for this design error, the licensee committed to continue 20-minute roving fire watches until such time that plant modifications to prevent this loss of pumps was completed.

Contrary to the above, at 2:00 p.m., on March 14, 1986, the roving fire watch was secured even though the plant modification for these pumps was not completed.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding this deviation, actions to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAY 15 1986

8605200185 860515  
PDR ADOCK 05000302  
Q PDR