Regulatory | File Cy.

PACIFIC GAS AND ELECTRIC COMPANY

IP G ME + 77 BEALE STREET . SAN FRANCISCO, CALIFORNIA 94106 . (415) 781-4211

JOHN C. MORRISSEY
VICE PRESIDENT AND GENERAL COUNSEL
MALCOLM H. FURBUSH
ASSOCIATE GENERAL COUNSEL
CHARLES T. VAN DEUB
MALCOLM A MACKILLO
PHILIPA. CRANE,
HENRY J. LAPLANTE
RICHARD A. CLARTE

PRII 9 1976

DORAGE L. MILLIAM RECEIVED AND RECEIVED AND RECEIVED AND REASON LIBERT CONTROL FERTING AND RECEIVED AND RECEI

BERNARD J. DELLASANTA HOWARD V. BOLUB JAMES C. LOSSDON LOUIS F. SCHOFFELD DENNIS C. SULLIVAN ROSEST L. HARRIS JACK W. SHUCK.

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
Region V
U. S. Nuclear Regulatory Commission

1990 North California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, California 94596

> Re: Docket No. 50-133 License No. DPR-7

Dear Mr. Engelken:

Pursuant to Section IX.I.2.a. of Appendix A to the Humboldt Bay Unit No. 3 Facility Operating License, we are submitting the enclosed Licensee Event Report for the increased leakage in the drywell. This event was reported to your staff by telephone and confirmed by telecopier on March 18, 1976.

Very truly yours,

Philip a. Grane, Jr.

Enclosure

CC w/enc.:

Director

Office of Management Information

and Program Control

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

3856



PACIFIC GAS AND ELECTRIC COMPANY

PGSE

77 BEALE STREET . SAN FRANCISCO, CALIFORNIA 94106 . (415) 781-4211

JOHN C. MORRISSEY VICE PRESIDENT AND GENERAL OCUNSEL MALCOLM H. FURBUSH ASSOCIATE GENERAL COUNSEL CHARLES T. VAN DEUSEN MALCOLM A. MACKILLOP PHILIPA CRANE. JR HENRY J. LAPLANTE RICHARD A. CLARKE JOHN B. GIDSON

March 31, 1976

NOEL KELLY EDWARD J. MCDANNEY ABYNJA L. MILLWAN, JA ROSERY DINISACH DAN DRAYSON LUSSUCK

Mr. R. H. Engelken, Director Office of Inspection and Enforcement Region V U. S. Muclear Regulatory Commission 1990 North California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, California 94596

> Re: Docket No. 50-133 License No. DPR-7



Dear Mr. Engelken:

Pursuant to Section IX.I.2.a. of Appendix A to the Humboldt Bay Unit No. 3 Facility Operating License, we are submitting the enclosed Licensee Event Report for the increased leakage in the drywell. This event was reported to your staff by telephone and confirmed by telecopier on March 18, 1976.

Very truly yours,

Philip A. Crane, Jr.

Enclosure

CC w/enc.: Director

Office of Management Information

and Program Control

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

