

## Power Generation Group

Perry Nuclear Power Plant 10 Center Road Perry, Ohio 44081 Mail Address: P.O. Box 97 Perry, OH 44081 216-259-3737 FAX: 216-280-8002

November 13, 1997 PY-CEI/NRR-2235L

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Perry Nuclear Power Plant Docket No. 50-440 License No. NPF-58 Monthly Operating Report

Ladies and Gentlemen:

Attached is the October 1997 Monthly Operating Report for Perry Unit 1. Page 1 is the Operating Data Report and page 2 is the Unit Shutdowns and Power Reductions Chart. This report is submitted in accordance with Technical Specification 5.6.4 and Generic Letter 97-02, "Revised Contents of the Monthly Operating Report."

If you have questions or require additional information, please contact Mr. Hal Coon at (216) 280-5434.

Very truly yours,

Henry L. Megrat

Manager - Regulatory Affairs

HMC:s

Attachment

cc: NRC Region III Administrator

NRC Project Manager NRC Resident Inspector

9711190029 971031 PDR ADDUK 05000440 PDR

lanin in inin'n'n'n

IE24

## **OPERATING DATA REPORT**

UNIT: Perry
DATE: 11/13/97

1. Docket: 50-440

w ....

2. Unit Name: Perry Nuclear Power Plant

3. Reporting Period: October 1997

4. Utility Contact: H.M. Coon

5. Telephone: 216-280-5434

Design Electrical Rating (Net MWe): 1191

7. Maximum Dependable Capacity (Net MWe): 1160

		This Month	Yr-to-Date	Cumulative	
8.	Hours Reactor was Critical	306.8	6,001.9	63.091.2	
9.	Hours Generator On-1Line	172.7	5.787.4	60.925.7	
10.	Unit Reserve Shutdown Hours	0.0	0.0	0.0	
11.	Net Electrical Energy (MWeH)	114,922	6,515,800	67,785,401	

## UNIT SHUTDOWNS AND POWER REDUCTIONS REPORT MONTH - OCTOBER 1997

DOCKET NO: 50-440

NAME: Perry Nuclear Power Plant

DATE: 11/13/97

CONTACT: H. M. Coon

TELEPHONE: (216) 280-5434

No.	Date	Type 1	Duration Hours	Reason 2	Method 3	Cause and Corrective Action to Prevent Recurrence
97-09	9/12/97	s	550.9	С	4	Refuel Outage #6.
97-10	10/26/97	F	17.0	A	1	Turbine outage due to Main Steam Drain Line leak
97-11	10/29/97	S	0	В	9	Planned downpower to adjust rodtern

SUMMARY: Perry Unit One was involved with refueling outage #6 until 10/23/97 at 2252 when the generator was synchronized to the grid. On 10/26/97 at 1309, the turbine was shutdown to repair a main steam drain line leak. The plant was synchronized to the grid at 0610 on 10/27/97. 100% power was achieved at 1723 on 10/28. A planned power reduction to adjust rod pattern was performed 10/29-30. 100% power was achieved at 0322 on 10/30. The unit remained at 100% power for the remainder of the month.

- 1. TYPE:
  - F: Forced
  - S: Scheduled
- 2 REASON
  - A Equipment Failure (explain)
  - B Maintenance or Test
  - C Refueling
  - D Regulatory Restriction
  - E Operating Training & License Examination
  - F Administrative
  - G Operational Error (explain)
  - H Other (explain)

- 3. METHOD:
  - 1 Manual
  - 2 Manual Scram
  - 3 Automatic Scram
  - 4 Continued
  - 5 Reduced Load
  - 9 Other