

DMB

JUN 13 1986

MEMORANDUM FOR: D. F. Humenansky, Technical Assistant, OCM
FROM: B. L. Burgess, Chief, Projects Section 2A, Division of
Reactor Projects
SUBJECT: COMMISSIONER ZECH'S VISIT TO PALISADES AND D. C. COOK

Attached is the itenerary for Commissioner Zech's visit to the Palisades and D. C. Cook plants on June 23 and 24, 1986. The times listed are proposed and can be changed as you desire. As we discussed earlier, A. B. Davis and I will provide transportation to and from the Kalamazoo Airport and during your visit.

Please feel free to call me (FTS 388-5689) should you have any questions.

B. L. Burgess, Chief
Projects Section 2A

Attachment: As Stated

cc w/attachment:
C. E. Norelius
A. B. Davis

8606180212 860613
PDR ADOCK 05000255
P PDR

BAB
RIII
Burgess
06/13/86

in
RIIF
Guldemond
6/13/86

JE01

Visit by Commissioner Zech

June 23 and 24, 1986

Palisades Itinerary

Monday, June 23, 1986

- 09:51 a.m. (EDT) Commissioner arrives in Kalamazoo, Michigan
- 10:15 a.m. Depart Kalamazoo Airport
- 11:45 a.m. Lunch in South Haven
- Senior Resident Inspector from Palisades to meet Zech party at restaurant
- 01:00 p.m. Arrive at Palisades site
- 01:10 p.m. Meet with utility for presentation (30-45 minutes)
- Presentation should include:
 - o Past, present and anticipated problems and corrective actions for each
 - o Transparencies for the following performance indicators:
 1. Unplanned trips
 2. LERs by cause code
 3. SRO/RO exam rates
 4. Liquid/Solid/Gaseous releases and exposure
 5. ESF Actuations
 - o Transparency on Organization (no more than two minutes)
 - o Training Accreditation Status
 - o Transparency on Shift Arrangement including names, experience and education
- 1:50 p.m. Plant Tour
- 45 minutes in control room
 - o interviews with shift engineer/shift supervisor (topics of discussion to include procedures, alarm and control board familiarity)

Palisades Itinerary

Monday, June 23, 1986

02:35 p.m.	Continue tour (Conducted by Plant Manager)
	Topics of Interest
	1. May 19 equipment failures
	2. Chemistry Labs
	3. Training
03:35 p.m.	Tour training building
	- 15 minute pep talk with all available operators
04:15 p.m.	Exit with licensee managers (45 minute presentation by Commissioner Zech)
05:00 p.m.	Depart site
07:00 p.m.	Dinner at Holidome or other acceptable restaurant

D. C. Cook Itinerary

Tuesday, June 24, 1986

07:00 a.m. (EDT) Breakfast at the Holidome (meet with Resident Inspectors)

08:00 a.m. Arrive at D. C. Cook site

8:15 a.m. Meeting for utility presentation (30-45 minutes)

- Presentation should include:

- ° Past, present and anticipated problem and corrective actions for each
- ° Transparencies for the following performance indicators:
 1. Unplanned trips
 2. LERs by cause code
 3. SRO/RO Exam rates
 4. Liquid/Solid/Gaseous releases and exposures
 5. ESF Actuations
- ° Transparency on Organization (no more than 2 minutes)
- ° Training accreditation status
- ° Transparency on shift arrangement (including names, experience and education)

09:00 a.m. Plant Tour
- 45 minutes in control room

- ° Interviews with shift supervisor/assistant shift supervisor/unit supervisor (topics of discussion to include procedures, alarms and control panel familiarity)

09:45 a.m. Continue Plant Tour (conducted by Plant Manager)

- Topics of Interest
 - ° Equipment problems related to recent events
 - ° Chemistry Labs
 - ° Training

11:15 a.m. Tour training building
- 15 minute pep talk with all available operators

11:45 a.m. Meet with licensee managers
- 45 minute presentation by Commissioner Zech

01:00 p.m. Depart site

02:30 p.m. Lunch in Kalamazoo (optional)

03:00 p.m. Commissioner departs Kalamazoo airport