
Boston Edison
Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

10 CFR 50.73

L.J. Olivier
Vice President Nuclear and Station Director

January
BECOLtr. 2.98.010

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 97-030-00, "Misapplication of FSAR Drywell Free Volume," is submitted in accordance with 10 CFR 50.73.

The following commitments are made in this letter:

- Revise FSAR Table 5.2.1 to clarify the listed drywell free volume value (March 30, 1998).
- Complete the drywell volume calculations, M776 and M777 (February 28, 1998).

Please do not hesitate to contact me if there are any questions regarding this report.


L.J. Olivier


KRD/dcg
Id. 97030000/ler

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECOLER Distribution

980204009 980123
PDR ADOCK 05000293
S PDR



1/1
1E22