NRC Form 591			U.S. NUCLEAR SE	GULATORY COMMISSION
12-81) 0 CFR 2.201	SAFETY I	SAFETY INSPECTION		DMB COPY
NOOTER CORPORATION 1400 S. 350 ST. ST. LOUIS, MISSOURI 63166		2. REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137		
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPE	CTION
030-05088	24-0378	3-01	MARCH	27,1986
<ul> <li>4. Within the scope of this inspection, no violation</li> <li>4. The inspector also verified the steps you have those actions at this time.</li> <li>3. During this inspection certain of your activitient of the steps with t</li></ul>	e taken to correct the violati es, as checked below, were	in violation of NRC rec	guirements. R 19.11. was not properly po	ve no further questions on sted to indicate the presen 203(b), (c), (d), (e) or 34.4 were not proper
frequencies. 10 CFR      D. Records of     10 CFR      E. Documents were not properly posted or o		or License Condition N		ere not properly maintaine
F. Reports or notifications of				
		ar License Condition N		were not made in accordan
П	960327 PDR			
hereby state that within 30 days the actions describe this statement of corrective actions is made in accord he NRC. SIGNATURE - LICENSEE		Colleen		submitted unless required 1