

Commonwealth Edison Company  
Byron Generating Station  
4450 North German Church Road  
Byron, IL 61010-9794  
Tel 815-234-5441

**ComEd**

January 6, 1999

LTR: BYRON 98-0324  
FILE: 2.01.0700

PRIORITY ROUTING

First		Second	
RA	<i>has</i>	RC	
DRA	<i>has</i>	EIC	
ORH	<i>has</i>	SGA	
DRP		OI	
ORS	<i>has</i>	PAO	
DNMS			
DRMA			

FILE *has*

James E. Dyer  
Region III Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
801 Warrenville Road  
Lisle, IL 60532-4251

Byron Station, Unit 1  
Facility Operating License No. NPF-37  
NRC Docket No. STN 50-454

SUBJECT: Steam Generator Replacement Outage Startup Report - Corrected  
Section 2.0

REFERENCE: ComEd letter, "Steam Generator Replacement Outage Startup Report,"  
dated June 3, 1998.

In the referenced letter, we submitted the Startup Report to summarize the startup and power escalation testing required as a result of the Steam Generator replacement modification for Byron Station Unit 1. Subsequent to the submittal we noticed several errors in Section 2.0 of the report, "Core Testing". The errors are administrative in nature that occurred during the transcription of data from source documents to the report and do not affect any of the report conclusions.

22003\*

9901250020 990106  
PDR ADOCK 05000454  
P PDR

p:\98byltrs\980324.wpf

A Unicom Company


JAN 13 1999

Page 2

Steam Generator Replacement

Please replace Section 2.0 of the original report in accordance with the attached update instructions. We apologize for any inconvenience this may cause you. Should you have any questions regarding this letter, please contact Joseph Langan at (815)234-5441, extension 2871.

Respectfully

A handwritten signature in cursive script, appearing to read "William Levis".

William Levis  
Station Manager  
Byron Station

Attachment

WL/JL/cb

cc: Byron Project Manager - NTR  
NRC Senior Resident Inspector - Byron Station  
Office of Nuclear Facility Safety - IDNS

Attachment

Corrected Pages to Byron Station Unit 1 Cycle 9 Startup Report



Update Instructions:

Remove

Insert

Title Page

Revised Title Page

Section 2, pages 2 through 9

New Section 2, pages 2 through 9