

IE07

# SAFETY AND COMPLIANCE INSPECTION

|  |                                     |   |  |
|--|-------------------------------------|---|--|
| 1. LICENSEE<br>WESTERN XRAY COMPANY<br>3663 BRANSON ROAD<br>POTEAU, OKLAHOMA 74953 |                                     | 2. REGIONAL OFFICE<br><br>REGION IV<br>US NUCLEAR REGULATORY COMMISSION<br>611 RYAN PLAZA DR STE 400<br>ARLINGTON TX 76011-8064 |  |
| REPORT NUMBER(S) 97-01   |                                     |   |  |
| 3. DOCKET NUMBER(S)<br>030-19640   | 4. LICENSE NUMBER(S)<br>35-19993-01 | 5. DATE(S) OF INSPECTION<br>12/16/97  |  |

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. \_\_\_\_\_ non-cited violation(s) were discussed involving the following requirement(s): \_\_\_\_\_
- ☒ 3. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11.

A. CONTRARY TO 10CFR 24.14(d)(1) THE LICENSEE FAILED TO PRESERVE A RADIOGRAPHIC DURING ACTIVE RADIOGRAPHIC EXAMINATION OF AN INTERNAL ACT TO EXCEED THREE MONTHS. SPECIFICALLY A RADIOGRAPHIC WAS TAKEN FOR RADIOGRAPHIC EXAMINATION IN MULTIPLE OCCASIONS BETWEEN 6/1/96 AND 6/27/96 AND HAD NOT BEEN PRESERVED BY THE LICENSEE SINCE 2/5/96. AN INTERNAL EXCEEDING THREE MONTHS.

B. CONTRARY TO 49CFR 172.403(d)(5) THE LICENSEE FAILED TO PROPERLY LABEL OVERPACKS WHICH CONTAINED PACKAGES FOR WHICH LABELS ARE REQUIRED. SPECIFICALLY OVERPACKS CONTAINING RADIOGRAPHIC DEVICES LOADED WITH RADIOACTIVE MATERIAL WERE NOT LABELED WITH TWO LABELS ON OPPOSITE SIDES.

C. CONTRARY TO 10CFR 24.20(b)(1)(iv) THE LICENSEE FAILED TO ENSURE THAT EACH RADIOGRAPHIC EXPOSURE DEVICE HAS ATTACHED TO IT A PERMANENT, LEGIBLE, CLEARLY VISIBLE LABEL BEARING THE LICENSEE'S NAME, ADDRESS AND TELEPHONE NUMBER.

9802090043 971216  
PDR ADOCK 03019640  
C PDR



## STATEMENT OF CORRECTIVE ACTIONS

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| TITLE         | PRINTED NAME | SIGNATURE          | DATE     |
|---------------|--------------|--------------------|----------|
| LICENSEE      | JAMES PETERS | <i>[Signature]</i> | 12/16/97 |
| NRC INSPECTOR | JEFFREY CHUB | <i>[Signature]</i> | 12/16/97 |