

P. R. MALLORY & CO. INC. LABORATORY FOR PHYSICAL SCIENCE Northwest Industrial Park, BURLINGTON, MASSACHUSETTS 01803, Telephone 617-272-4100

April 7, 1975

U. S. Nuclear Regulatory Commission Division of Material Licensing Washington, D. C. 20545

Dear Sirs:

Our company transferred the operations of its analytical laboratory from Indianapolis, Indiana to Burlington, Massachusetts. One item of laboratory test equipment -- a Varian Aerograph gas chromatograph Model 284030/00 -contained a nickel 63 foil detector cell controlled under U.S. AEC Byproduct Materials License #13-03022-02 dated March 28, 1972.

Since several personnel changes occurred at the time of the laboratory transfer, we unfortunately were not aware that the item was under license until it was recently unpacked at our Burlington location. In checking the license we found that we had violated conditions #10 and #12 regarding location and supervision of the device. On March 19, 1975 the attached letter was sent to the AEC requesting a license revision.

Following this, I was contacted by Mr. Ronald Paul of the U.S. NRC in Chicago, and I have since contacted Mr. Robert McClintock of the Region I office in King of Prussia, Pa. It was suggested that I contact your division to request a transfer of the license to the new location.

Let me affirm that the intended use of the device in question is unchanged and that the only revisions requested are in the physical location of the gas chromatograph and the supervisors of the operation.

In reference to Form 313, the following items are affected:

Item 1 (a) (b) Applicant

New P. R. Mallory & Co. Inc. Laboratory for Physical Science Third Avenue Burlington, Mass. 01803


Old P. R. Mallory & Co. Inc. P. O. Box 706 3029 E. Washington St. Indianapolis, Ind. 46206

## Item 2 Department

Laboratory for Physical Science

Technical Services Laboratory

8604100297 860213 REG1 LIC30 20-03022-03 PDF



U. S. Nuclear Regulatory Commission Page Two April 7, 1975

Item 4 Users

New Dr. R. Selin Dr. P. Bro Old F. H. Sauer M. Turley

55630

All other items are as specified in the original Form 313 dated 22 February 1972, copy enclosed.

The Chicago office is in the process of issuing a notice of non-compliance for violation of condition 10 of the license. You may be assured that the violation was not an intentional one. We are most anxious to have the matter resolved as quickly as possible, and will await your recommendations.

Very truly yours,

P. R. MALLORY & CO. INC. Laboratory for Physical Science

lindus

Dennis C. Jedlinsky Manager-Administration

encl. DCJ:md

CC: Mr. Ronald Paul U. S. Nuclear Regulatory Commission 799 Roosevelt Rd. Glen Ellyn, Illinois

> Mr. Robert McClintock U. S. Nuclear Regulatory Commission King of Prussia, Pennsylvania