James A. FitzPatrick Nuclear Power Plant 268 Lake Road P.O. Box 41 Lycoming, New York 13093 315-342-3840



November 21, 1997 JAFP-97-0455 Michael J. Colomb Site Executive Officer

United States Nuclear Regulatory Commission Attn: Document Control Desk

Mail Station P1-137 Washington, D.C. 20555

Subject:

Docket No. 50-333

LICENSEE EVENT REPORT: LER-97-011

Invalid ESF Actuation and Failure to Perform Technical Specification Required Actions While Performing Troubleshooting Activities

Dear Sir:

This report is submitted in accordance with 10 CFR Part 50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications". This report is also being submitted in accordance with 10 CFR Part 50.73(a)(2)(iv), "Any event or condition that resulted in a manual or automatic actuation of any engineered safety feature (ESF) including the reactor protection system (RPS).

There are no commitments contained in this report.

Questions concerning this report may be addressed to Mr. Richard Plasse at (315) 349-6793.

Very truly yours,

MICHAEL J. COLOMB

MJC:RAP:las Enclosure

CC:

USNRC, Region 1

USNRC Resident Inspector INPO Records Center

9712030147 971121 PDR ADOCK 05000333 S PDR IEDOY,

