

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE, ILLINOIS 60532-4351

February 3, 1998

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT:

NOTICE OF VIOLATION AND NRC INSPECTION REPORT

NO. 50-454/97024(DRP); 50-455/97024(DRP)

Dear Mr. Kingsley

On January 12, 1998, the NRC completed an inspection at your Byron 1 and 2 reactor facilities. The enclosed report presents the inspection results.

During the inspection period, your conduct of activities at the Byron facility was generally characterized by safety-conscious operations. Main control room activities were performed well, including annunciator alarm response, communications between operators, and supervisory oversight. Operators also maintained an awareness of activities that could influence the safety of each unit. The large number of activities associated with the Unit 1 steam generator replacement project did not impact Unit 2 operation. Your staff maintained easy access to structures, systems and components for operators. Common area housekeeping was also good with equipment appropriately staged or secured. Outage related material was properly controlled with the exception of two separate failures to control transient combustibles.

Based on results of this inspection, the NRC has determined that two violations of NRC requirements occurred. The violations are cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding them are described in detail in the subject inspection report. Both violations involved the failure to control transient combustible material in accordance with station procedures and were identified by the NRC. The violations are of concern because control of combustible material is a significant part of fire prevention and mitigation.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

130008

Jeal



In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room.

Sincerely,

/s/ M. L. Dapas for

Geoffrey E. Grant, Director, Division of Reactor Projects

Docket Nos. 50-454: 50-455 License Nos. NPF-37; NPF-66

Enclosures:

1. Notice of Violation

2. Inspection Report

No. 50-454/97024(DRP); 50-455/97024(DRP)

cc w/encl.:

M. Wallace, Nuclear Services Sanior Vice President

G. Stanley, PER Vice President J. Perry, BAR Vice President

D. Fairer, Regulatory Services Manager

I. Johnson, Licensing Director

DID - Licensing

K. Grassier, Site Vice President K. Kofron, Station Manager D. Brindle, Regulatory Assurance

Supervisor Richard Hubbard

Nathan Schloss, Economist Office of the Attorney General

State Liaison Officer

State Liaison Officer, Wisconsin Chairman, Illinois Commerce

Commission

DOCUMENT NAME: G:\BYRO\BYR97024.DRP SEE PREVIOUS CONCURRENCES

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII	RIII	Riff	RIII	ERIII
NAME	Tongua/co	Gardner Violation & Sect F1.1	Shear Sect RI.2	Jordan A	Grant for
DATE	01/ /98	01/ /98	01/ /98	01/36/98	91/3/98

OFFICIAL RECORD COPY

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room.

Sincerely,

Geoffrey E. Grant, Director, Division of Reactor Projects

Docket Nos. 50-454; 50-455 License Nos. NPF-37; NPF-66

Enclosures: 1. Notice of Violation 2. Inspection Report

 Inspection Report No. 50-454/97024(DRP); 50-455/97024(DRP)

cc w/encl: M. Wallace, Nuclear Services
Senior Vice President

G. Stanley, PWR Vice President J. Perry, BWR Vice President

D. Farrar, Regulatory
 Services Manager

I. Johnson, Licensing Director

DCD - Licensing

K. Graesser, Site Vice Fresident K. Kofron, Station Manager D. Brindle, Regulatory Assurance

Supervisor Richard Hubbard

Nathan Schloss, Economist Office of the Attorney General

State Liaison Officer

State Liaison Officer, Wisconsin Chairman, Illinois Commerce

Commission

DOCUMENT NAME: G:\BYRO\BYR97024.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = Ne copy

OFFICE RIII
NAME Tongu

s Barrut

RIII Shear

RIII

RIII

DATE

Tongue

01/16/98

Gardner Violation & Sect F1.1

01/26/98

Sect RI.2

01/26/98

01/ /98

OFFICIAL RECORD COPY

Distribution:
Docket File w/encls
PUBLIC IE-01 w/encls

A. Beach w/encl
Deputy RA w/encls
RIII Enf. Coord. w/encls
SRI Byron w/encls
Project Mgr., NRR w/encls

DRP w/encls TSS w/encls DRS (2) w/encls RIII PRR w/encls RAC1 (E-Mail) CAA1 (E-Mail) DOCDESK (E-Mail)