NRC Form 591	61 63		U.S. NUCLEAR REGULATORY COMMISSION
12.81) 10 CFR 2.201	SAFETY I	NSPECTION	U.S. NOCLEAR RECOVERTON COMMONICA
Grizzly Enginee 751 S. Sheridan A Shevidan, Wyoming	ve. 82801	Region IV	Regulatory Commission a Drive, Suite 1000 exas 76011
30 - 20331	4 LICENSE NUMBERIS 49-23166		March 27, 1986
icensee			
 he inspection was an examination of the activities of legulatory. Commissions' (NRC) rules and regulation and representative records, interviews, with personne	is and the conditions of yo el, and observations by the ons were observed.	ur license. The inspection inspector. The findings ai	consisted of selective examinations of procedures
3. During this inspection certain of your activitie THIS IS A NOTICE OF VIOLATION which			
A1			_ was not properly posted to indicate the presence
of a		A	10 CFR 20.203(b), (c), (d), (e) or 34 42
C			of sealed sources were not performed at the proper ndition Number
D. Records of			
10 CFR		or License Condition Num	were not properly maintained
E. Documents were not properly posted or o	therwise made available.	0 CFR 19.11.	
F. Reports or notifications of with 10 CFR		or License Condition Nun	were not made in accordance
TH. Shipping papers ha in accordance 6	ith 49 (F	Propared for R 172	or each shipment
L			
REGA	4140089 86032 4 LIC30 23166-01 P	DR	1×10
			he violations identified in the items checked above. Further response will be submitted unless required b
SIGNATURE - LICENSEE	3.27.86 DATE	Willy	Le Holley 3/27/86