


Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

L. J. Olivier

Vice President Nuclear Operations
and Station Director

November 28, 1997
BECO Ltr. 2.97.11P

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

Docket No. 50-291
License No. DPR-

The enclosed Licensee Event Report (LER) 97-022-00, "Temporary Power Cables and Extension Cords Found Draped or Tie Wrapped To Class 1E Conduits in the Reactor Building in Violation of Electrical Separation Criteria," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitments:

- Procedure 3.M.3-36, "Control of Temporary Power," that governs temporary power will be revised to incorporate necessary guidance regarding electrical separation with respect to the use of temporary power cables.
- A policy statement will be issued to station personnel regarding the use of temporary power cables and extension cords.

Please do not hesitate to contact me if there are any questions regarding this report.

L. J. Olivier
L. J. Olivier

RLC/dmc/9702200

Enclosure: LER 97-022-00

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECO LER Distribution

9712090045 971128
PDR ADOCK 05000293
S PDR

