

EVALUATION RESEARCH CORPORATION

CONTROLLED COPY
CONTROL NO. PF001

COMANCHE PEAK RESPONSE TEAM

QUALITY INSTRUCTION FOR ISSUE-SPECIFIC ACTION PLAN ISAP VII.b.4

CHANGE NOTICE: 001

INSTRUCTION NO.: QI-063

REVISION NO.: 1

ISSUE DATE: 2/10/86

CONTROLLED COPY
CONTROL NO. QI-001

REINSPECTION OF TORQUE FOR DRILLED-IN CONCRETE
EXPANSION ANCHORS (HILTI BOLTS)

The QI identified above is hereby changed as
shown on the attached page of this notice.

Prepared by: S.H. Popper
Issue Coordinator

Date: 2/7/86

Approved by: D.J. Alexander
Hardware Supervisor *at client*

Date: 2/7/86

Approved by: G.W. Parr
On-Site QA Representative

Date: 2-10-86

Approved by: J. Schuster
QA/QC Review Team Leader

Date: 2/10/86

1. Revise 5.5 to read:

"Verify bolt torque satisfies the acceptance value, ± 1 ft-lb, given in Table II of Attachment 6.2 using a calibrated dial indicating torque wrench,..."