



Gary R. Peterson  
Vice President

Duke Power Company  
A Duke Energy Company

Catawba Nuclear Station  
4800 Concord Road  
York, SC 29745

(803) 831-4251 OFFICE  
(803) 831-3426 FAX

February 12, 1998

U.S. Nuclear Regulatory Commissio..  
Document Control Desk  
Washington, D.C. 20555


Subject: Catawba Nuclear Station, Unit 1  
Docket No. 50-413  
Revision to Special Report  
Steam Generator Tube Inspection

In my letter of January 26, 1998 the results of the steam generator tube inspections conducted during the Unit 1 End of Cycle 10 refueling outage were reported. In that letter, the number of tubes inspected was incorrectly reported. The correct number of tubes inspected is as follows:

<u>Steam Generator</u>	<u>Tubes Inspected</u> <u>Full Length</u>
A	6625
B	6633
C	6626
D	6629


There is no change to the information provided in my January 26, 1998 letter on size and location of tube imperfections. If additional information on this matter is required, please contact G.A. Copp at (803)831-3622.

Very truly yours,

  
G. R. Peterson

10  
Add

40009  
9802240182 980212  
PDR ADOCK 05000413  
P PDR



U.S. Nuclear Regulatory Commission  
February 12, 1998  
Page 2

xc: Mr. P.S. Tam, NRC Project Manager  
Office of Nuclear Reactor Regulation

Mr. L.A. Reyes, Regional Administrator  
U.S. Nuclear Regulatory Commission, Region II

Mr. D.J. Roberts, Senior Resident Inspector  
Catawba Nuclear Station