

JUL 16 1986

Docket No. 50-455

Commonwealth Edison Company
 ATTN: Mr. Cordell Reed
 Vice President
 Post Office Box 767
 Chicago, IL 60690

Gentlemen:

This refers to the special safety inspection conducted by Mr. J. M. Hinds, Jr. and Ms. J. A. Malloy of this office on June 23 - July 8, 1986, of activities at Byron Station Unit 2, authorized by NRC Construction Permit No. CPPR-131 and to the discussion of our findings with Mr. V. I. Schlosser and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed W. L. Forney

8607210123 860716
 PDR ADOCK 05000455
 Q PDR

R. F. Warnick, Chief,
 Reactor Projects Branch 1

Enclosure: Inspection Report
 No. 50-455/86021(DRP)

See Attached Distribution

RIII

WJH
 Hinds/jp

RIII

WJH
 Lerch

RIII

WJH
 Forney
 7/15

RIII

WJH
 Warnick

IEU1

2 JUL 16 1986

Distribution:

cc w/enclosure:

D. L. Farrar, Director
of Nuclear Licensing

V. I. Schlosser, Project Manager
Gunner Sorensen, Site Project
Superintendent

R. E. Querio, Plant Manager
DCS/RSB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood

Phyllis Dunton, Attorney
General's Office, Environmental
Control Division

D. W. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE
Steve Lewis, ELD

L. Olshan, NRR LPM
H. S. Taylor, Quality Assurance
Division
TSS, RIII