

DMO

JUL 15 1986

Docket No. 50-454

Commonwealth Edison Company  
ATTN: Mr. Cordell Reed  
Vice President  
Post Office Box 767  
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. M. Hinds, Jr., P. G. Brochman, L. N. Olshan, and Ms. J. A. Malloy of this office on May 31 through June 30, 1986 of activities at Byron Station, Unit 1, authorized by NRC Operating License No. NPF-37 and to the discussion of our findings with Mr. R. E. Querio and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by W. L. Forney

R. F. Warnick, Chief  
Reactor Projects Branch 1

Enclosure: Inspection Report  
No. 50-454/86021(DRP)

See Attached Distribution

RIII

WJ  
Hinds/kst

RIII

WJ  
Lerch

RIII

WJ  
Forney

RIII

WJ  
Warnick

RIII

Pirtle  
7/13/86

LEO

B607210136 B60715  
PDR ADOCK 05000454  
Q PDR

JUL 15 1986

Distribution

cc w/enclosure:

D. L. Farrar, Director  
of Nuclear Licensing

V. I. Schlosser, Project Manager

Gunner Sorensen, Site Project  
Superintendent

R. E. Querio, Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII Byron

Resident Inspector, RIII  
Braidwood

Phyllis Dunton, Attorney

General's Office, Environmental  
Control Division

D. W. Cassel, Jr., Esq.

Diane Chavez, DAARE/SAFE

Steve Lewis, ELD

L. Olshan, NRR LPM

H. S. Taylor, Quality Assurance  
Division