



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

February 12, 1999

Harold B. Ray, Executive Vice President
Southern California Edison Co.
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, California 92674-0128

SUBJECT: NRC INSPECTION REPORT 50-361/98-22; 50-362/98-22 AND NOTICE OF VIOLATION

Dear Mr. Ray:

Thank you for your letter of January 26, 1999, which clarified details related to corrective actions taken by you in response to two violations discussed in the report. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

A handwritten signature in cursive script, appearing to read "Gail M. Good".

Gail M. Good, Chief
Plant Support Branch
Division of Reactor Safety

Docket Nos.: 50-361
50-362
License Nos.: NPF-10
NPF-15

cc:
Chairman, Board of Supervisors
County of San Diego
1600 Pacific Highway, Room 335
San Diego, California 92101

Alan R. Watts, Esq.
Woodruff, Spradlin & Smart
701 S. Parker St. Suite 7000
Orange, California 92868-4720

9902220106 990212
PDR ADOCK 05000361
G PDR

Southern California Edison Co.

-2-

Sherwin Harris, Resource Project Manager
Public Utilities Department
City of Riverside
3900 Main Street
Riverside, California 92522

R. W. Krieger, Vice President
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, California 92674-0128

Stephen A. Woods, Senior Health Physicist
Division of Drinking Water and
Environmental Management
Nuclear Emergency Response Program
California Department of Health Services
P.O. Box 942732, M/S 396
Sacramento, California 94334-7320

Mr. Michael R. Olson
Sr. Energy Administrator
San Diego Gas & Electric Company
P. O. Box 1831
San Diego, California 92112-4150

Mr. Steve Hsu
Radiological Health Branch
State Department of Health Services
P.O. Box 942732
Sacramento, California 94234

Mayor
City of San Clemente
100 Avenida Presidio
San Clemente, California 92672

Mr. Truman Burns\Mr. Robert Kinosian
California Public Utilities Commission
505 Van Ness, Rm. 4102
San Francisco, California 94102

DISTRIBUTION w/copy of licensee's letter dated January 26, 1999:

DCD (IE06)

Regional Administrator

SONG Resident Inspector

DRP Director

DRS-PSB

DRS Director

Branch Chief (DRP/E)

Senior Project Inspector (DRP/E)

Branch Chief (DRP/TSS)

MIS System

RIV File

DOCUMENT NAME: R:_SO23\SO822AK.LTR

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PSB	E	C:DRS\PSB	N						
*LTRicketson:nh		GMGood	GRB						
02/ /99		02/2/99							

*Previously concurred.

OFFICIAL RECORD COPY

DISTRIBUTION w/copy of licensee's letter dated January 26, 1999:

DCD (IE06)

Regional Administrator

SONG Resident Inspector

DRP Director

DRS-PSB

DRS Director

Branch Chief (DRP/E)

Senior Project Inspector (DRP/E)

Branch Chief (DRP/TSS)

MIS System

RIV File


DOCUMENT NAME: R:_SO23\SO822AK.LTR

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PSB	E	AC:DRS/PSB	D:DRS						
LTRicketson:nh		JBNicholas	ATHowell III						
02/9/99		02/9/99	02/ /99						

OFFICIAL RECORD COPY

January 26, 1999



U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Reply to a Notice of Violation
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, Mr. Arthur T. Howell (USNRC) to Mr. Harold B. Ray
(SCE), dated January 7, 1999

The referenced Inspection Report and Notice of Violation cover letter indicates "... you are not required to respond to this letter unless the description therein does not accurately reflect your corrective actions or your position." Southern California Edison (SCE) has reviewed the Inspection Report and while the report does accurately reflect SCE's position relative to the violations themselves, SCE would like to clarify two of the corrective actions associated with the first violation mentioned in the Inspection Report (Violation 50-361/9822-01).

The first violation occurred during the week of the inspection, and involved the detachment of a high radiation area sign and rope barrier for a short period of time. As a part of the corrective actions which were developed prior to the inspector leaving the site, a standown of appropriate contract workers was to be conducted and an article discussing the occurrence was to be placed in the site news letter.

Relative to the standown, during discussions with the inspector the impression was given that all contractors would participate in the standown and that the Maintenance Manager, Construction Manager, and the Radiation Protection Manager would discuss the occurrence and the importance of complying with radiation protection work requirements. The inspection report reflects this and it further states that the standown was conducted on December 15, 1998.

January 26, 1999

The standown was implemented as follows:

- The SONGS Maintenance Manager, Construction Manager, and the Radiation Protection Manager met with Bechtel Construction Company (BCC) non-manual field engineers, superintendents, general foremen and foremen, and conducted "stand-down training" on December 15, 1998.
- On December 15, 1998, standowns of approximately 300 BCC craft, BCC non-manual and nuclear construction non-manual personnel who are involved in field activities were conducted by the above trained personnel.


The importance of maintaining radiological barriers and complying with radiation protection work requirements was reiterated in a January 1, 1999, Health Physics Bulletin to RCA Personnel as well as a January 11, 1999, site news letter article. As discussed in the Inspection Report, SCE is conducting a review of radiation worker practices and root cause analysis of associated problems [referred to as an Event Trend Report (ETR)]. The ETR is currently scheduled for completion by the end of February, 1999. Additional corrective actions may be taken if deemed appropriate.

Relative to the news letter article, the information given to the inspector and reflected in the Inspection Report was that the article would appear in the January 4, 1999, edition. The article appeared in the January 11, 1999, news letter rather than the January 4, 1999 edition.

SCE does not believe that these clarifications change the characterization of the violations.

If you have any questions, please contact us.

Sincerely,



cc: E. W. Merschoff, Regional Administrator, NRC Region IV
L. J. Smith, Acting Chief, Branch E Division of Reactor Projects
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units 2 and 3
J. W. Clifford, NRC Project Manager, San Onofre Units 2 and 3

DISTRIBUTION w/copy of licensee's letter dated January 26, 1999:

DCD (IE06)

Regional Administrator

SONG Resident Inspector

DRP Director

DRS-PSB

DRS Director

Branch Chief (DRP/E)

Senior Project Inspector (DRP/E)

Branch Chief (DRP/TSS)

MIS System

RIV File

DOCUMENT NAME: R:_SO23\SO822AK.LTR

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PSB	E	C:DRS\PSB	N						
*LTRicketson:nh		GMGood	6/6						
02/ /99		02/7/99							

*Previously concurred.

OFFICIAL RECORD COPY

220020