



Commonwealth Edison

One First National Plaza, Chicago, Illinois

Address Reply to: Post Office Box 767

Chicago, Illinois 60690 - 0767

DMB

August 15, 1986

Mr. James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Braidwood Station Units 1 and 2
Supplemental Information to Inspection Report Nos.
50-456/85-015 and 50-457/85-016
NRC Docket Nos. 50-456 and 50-457

Dear Mr. Keppler:

The subject inspection report contained a violation identified by NRC Inspector R.D. Schulz which dealt with the failure to adequately control modifications to structural beams. This violation was closed in NRC Inspection Report No. 456/85-052; 457/85-050, based on close-out of Commonwealth Edison Nonconformance Report (NCR) #740, which identified forty-nine (49) unauthorized beam modifications, forty-seven (47) of which were "accepted-as-is" and two (2) which required reinforcement to restore the design margin.

Due to previous commitments, additional information relating to the issue is being provided. Subsequent to close-out of the above item, other activities prompted the Project Construction Superintendent to direct a 100% walkdown of the floor drain systems. It was during this walkdown that two additional unauthorized beam modifications were identified. These two instances were addressed on Commonwealth Edison Co. NCR #806 and dispositioned "accept-as-is" by Sargent & Lundy.

Based on the actions taken, Commonwealth Edison Co. believes that the total population of unauthorized beam modifications, isolated to the floor drain systems, have been identified and resolved. In addition, procedural and training requirements currently in place should preclude the recurrence of unauthorized beam modifications.

IEO1

8608220259 860815
PDR ADOCK 05000496
G PDR

AUG 18 1986

10

If you have any further questions on this matter, please direct them to this office.

Very truly yours,

Anthony Miosi
for D.L. Farrar
Director of Nuclear Licensing

DLF/pav

Enclosure

cc: NRC Resident Inspector - Braidwood
1983K