

March 10, 1999

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001

ULNRC-3978



Gentlemen:

**DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
UNION ELECTRIC CO.
FACILITY OPERATING LICENSE NPF-30
LICENSEE EVENT REPORT 98-001-01
TECHNICAL SPECIFICATION 3.8.1.1 VIOLATION DUE TO INOPERABLE
EMERGENCY EXHAUST SYSTEM AND MISSED TECHNICAL
SPECIFICATION 4.7.7.b.2 EMERGENCY EXHAUST SURVEILLANCE**

This letter transmits LER 98-001-01. This revision is submitted to clarify the scope of the original reviews performed for corrective action number three specified in LER 98-001-00. Subsequently, additional reviews of technical specification amendments issued since January 1, 1993 have been performed to more restrictive criteria. These reviews identified a case of failure to properly establish equipment operability within the allowed implementation period. This concern has been documented in LER 99-001-00 and is mentioned in the corrective action section of this LER for completeness.

We are sorry for any inconvenience this may cause you.

A handwritten signature in black ink that reads "R. D. Affolter".

R. D. Affolter
Manager, Callaway Plant

RDA/cjd

Enclosure

9903240143 990310
PDR ADOCK 05000483
S PDR

IE 22 1/1

ULNRC-3978
March 10, 1999
Page 2

cc: Mr. Ellis W. Merschoff
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Melvin K. Gray (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 13E16
Washington, DC 20555-2738

Manager, Electric Department
Missouri Public Service Commission
PO Box 360
Jefferson City, MO 65102

Records Center
Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, GA 30339