

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-346/86017(DRSS)

Docket No. 50-346

License No. NPF-3

Safeguards Group IV

Licensee: Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, OH 43652


Facility Name: Davis-Besse Nuclear Power Station, Unit 1

Inspection At: Davis-Besse Site, Oak Harbor, OH


Inspection Conducted: June 9-13, 1986 onsite and July 15, 1986 at the
Region III office.

Date of Last Physical Security Inspection: January 6-10, 1986

Inspectors:



B. Drouin
Physical Security Inspector

7/24/86
Date


G. M. Christoffer
Physical Security Inspector

7/24/86
Date

Approved By:


R. Creed
Safeguards Section

7/29/86
Date

Inspection Summary

Inspection on June 9-13 and July 15, 1986 (Report No. 50-346/86017(DRSS))

Areas Inspected: Included a Review of Management Effectiveness; Security Organization; Security Program Audit; Records and Reports; Testing and Maintenance; Physical Barriers - Protected and Vital Areas; Access Control - Personnel; Detection Aids - Protected Areas; Personnel Training and Qualification with particular interest in the Security Contingency Force; Security Contingency Plan and followup on IE Information Notices. The inspection also included a review of the impact of the ongoing strike on the Security program and a liaison visit to the Sheriff of Ottawa County, Ohio.

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

8608040084 860729
PDR ADOCK 05000346
Q PDR

Results: The licensee was found to be in compliance in 9 of 11 inspected areas with NRC requirements during this inspection except as noted below:

Access Control - Personnel: (1) access to a vital area was not adequately controlled; (2) An individual was not properly escorted.

Records and Reports: A security event was not reported in a timely manner.

In addition, two open items in the areas of management effectiveness and testing and maintenance were identified.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled