LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M I D C C 2 2 0 0 - 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5 57 CAT 58
REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 4 1 4 8 3 8 0 4 1 9 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  DURING NORMAL OPERATIONS, WHILE PERFORMING A NON-ROUTINE TEST, THE CABLE VAULT HALON
SYSTEM FAILED TO MEET THE DESIGN CONCENTRATIONS, AND WAS DECLARED INOPERABLE. THIS IS
CONTRARY TO T.S. 3.7.9.4. THE PROVISIONS OF ACTION ITEM "A" OF T.S. 3.7.9.4 WERE
INSTITUTED AT THIS TIME AND WILL CONTINUE IN EFFECT UNTIL THE SYSTEM IS RETURNED TO
O T6 OPERABLE STATUS. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
07
08
7 8 9  SYSTEM CAUSE CODE SUBCODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  A B 11 X 12 X 13 X X X X X X X X X X X X X X X X X
THE CAUSE FOR THIS SYSTEM TO FAIL TO ACHIEVE DESIGN CONCENTRATION HAS NOT BEEN
DETERMINED AT THIS TIME. REVIEW OF TEST DATA AND FURTHER SYSTEM REVIEW AND TESTING
WILL CONTINUE. FURTHER REPORTS WILL BE FORWARDED UNDER THE REQUIREMENTS ESTABLISHED
BY TECHNICAL SPECIFICATIONS.
1 3 BY TECHNICAL SPECIFICATIONS.
7 8 9 FACILITY STATUS  STATUS  N/A  OTHER STATUS  OTHER ST
7 8 9 10 12 13 44 45 46 80  RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36)  7 8 9 10 11 11 44 45 46 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) N/A  7 8 9 PERSONNEL INJURIES 13 80
1 8 0 0 0 0 0 0 N/A  7 8 9 11 12 N/A
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION  N/A  S  S  S  S  S  S  S  S  S  S  S  S  S
PUBLICITY ISSUED DESCRIPTION 45 N/A N/A
7 8 9 10 68 69 80.5  NAME OF PREPARER Paul Jacques PHONE 616-465-5901