



**PUBLIC
SERVICE
INDIANA**

S. W. Shields
Senior Vice President -
Nuclear Division

April 22, 1983
S83-16
SVP-0024-83

Mr. James G. Keppler,
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
Glen Ellyn, Illinois 60137

Docket Nos.: STN 50-546
STN 50-547
Construction Permit Nos.:
CPPR - 170
CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:

On March 25, 1983, Mr. L. G. Yeager of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). ITT Grinnell notified PSI of the potential for an interference to exist between the rear attachment brackets and the ITT Grinnell Figure 306/307 mechanical snubber pivot mount brackets. These interferences could restrict the movement of the snubber to less than the designed movement of five degrees minimum. An inspection performed by ITT Grinnell personnel at Marble Hill verified the presence of unacceptable snubber conditions at Marble Hill.

As a result of the above mentioned inspection, PSI will return the rear brackets to ITT Grinnell for reworking to bring them into compliance with design requirements.

This letter is intended to fulfill the requirements of a final report as required by 10 CFR 50.55(e). If you have any questions regarding this matter, please contact me at your convenience.

Sincerely,

S. W. Shields

SWS/LGY/bak

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin
J. F. Schapker

8305020118 830422
PDR ADDCK 05000546
PDR

IE27
APR 25 1983