IE07

RC FORM 591 PART 1				U.S. NUCLEAR REGULAT	ORY COMMISSION
CFR 2.201	CAL	ETY AND COM	DI IANCE INC	DECTION	
	SAF	ETY AND COMP	PLIANCE INS	PECTION	
Anderson Engineering Consultants 10205 Rockwood Road Little Rock, Arkansas 72204			2. REGIONAL OFFICE REGION IV US NUCLEAR REGULATORY COMMISSION 611 RYAN PLAZA DR STE 400 ARLINGTON TX 76011-8064		
DOCKET NUMBER(S) 98	NAME OF THE OWNER, WHEN PERSON AND PARTY OF THE OWNER, WHEN PERSON	4. LICENSE NUMBER(S)	0-01	5 DATE(S) OF INSPECTION DECEMBET 10,	1998
ICENSEE: he inspection was an examir legulatory Commission (NRC	nation of the activities	s conducted under your lice	ense as they relate to our license. The insp	radiation safety and to compliance wi ection consisted of selective examina pection findings are as follows:	th the Nuclear
4-8		violations were identified.			
2. The violation(s), non-repetitive, an discretion, were s	nd corrective action w	ras or is being taken, and the	ne remaining criteria i	are not being cited because they wer in the NRC Enforcement Policy, NUR ing the following requirement(s):	e self-identified, EG-1600, to exercise
		activities, as described bel ON, which is required to be		vere in violation of NRC requirements se with 10 CFR 19.11.	and are being cited.
	4				
29	30063				
9903290184	981210	Section of the Control of the Contro			
PDR ADDCK	03030424 PDR				
			ctor will be taken to co	CTIONS prrect the violations identified. This saken, corrective steps which will be to	
compliance will be achieved)		no further written response	to NRC will be require	ed, unless specifically requested.	
LICENSEE		PRINTED NAMI		SIGNATURE	DATE
NRC INSPECTOR	RZ	EVans/EMGO	ireia Ri	averal Bridge M Saven	12/10/98