

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power Corporation  
Crystal River

Docket No. 50-302  
License No. DPR-72

During the Nuclear Regulatory Commission (NRC) inspection conducted on August 13 - September 16, 1988, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1988), the violation is listed below:

10 CFR 50.73 (a)(2)(1)(B) requires the submittal of a Licensee Event Report (LER) within 30 days of the event for any operation or condition prohibited by the plant's Technical Specifications (TS).

Contrary to the above, as of September 16, 1988, a LER has not been submitted for a condition identified on July 12, 1988 in which containment air lock seal leakage tests previously performed were determined to be inadequate to implement the requirements of the TS.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Florida Power Corporation is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, Crystal River 3, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) admission or denial of the alleged violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time. If an adequate


Florida Power Corporation  
Crystal River

4

Docket No. 50-302  
License No. DPR-72

reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION



Bruce A. Wilson, Chief  
Reactor Projects Branch 2  
Division of Reactor Projects

Dated at Atlanta, Georgia  
this 9<sup>th</sup> day of October 1988

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power Corporation  
Crystal River

Docket No. 50-302  
License No. DPR-72

During the Nuclear Regulatory Commission (NRC) inspection conducted on August 13 - September 16, 1988, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1988), the violation is listed below:

10 CFR 50.73 (a)(2)(i)(B) requires the submittal of a Licensee Event Report (LER) within 30 days of the event for any operation or condition prohibited by the plant's Technical Specifications (TS).

Contrary to the above, as of September 16, 1988, a LER has not been submitted for a condition identified on July 12, 1988 in which containment air lock seal leakage tests previously performed were determined to be inadequate to implement the requirements of the TS.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Florida Power Corporation is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, Crystal River 3, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) admission or denial of the alleged violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time. If an adequate


Florida Power Corporation  
Crystal River

4

Docket No. 50-302  
License No. DPR-72

reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION



Bruce A. Wilson, Chief  
Reactor Projects Branch 2  
Division of Reactor Projects

Dated at Atlanta, Georgia  
this 5<sup>th</sup> day of October 1988