Official August 4, 1986 Docket Nos. 50-413, 50-414 License Nos. NPF-35, NPF-48 Duke Power Company ATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242 Gentlemen: SUBJECT: NRC AUGMENTED INSPECTION TEAM REPORT NOS. 50-413/86-25 AND 50-414/86-27 DATED JULY 25, 1986 On July 25, 1986, NRC transmitted the subject report of NRC inspection conducted at your Catawba facility. The inspection report contained photographs (Figures 2 through 6) which were not clear. Additionally, the report incorrectly identified an inspector followup item for item d. of paragraph 11 on page 27. The inspector followup item should have been identified for item f. of paragraph 11 on page 28. Please replace pages 27 and 28 and Figures 2 through 6 of the subject report with the enclosed pages. In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room. Should you have any questions concerning this letter, please contact us. Sincerely, Original Signed by Roger D. Walker /for J. Nelson Grace Regional Administrator Enclosures: Revised Pages 27 and 28 of Inspection Report Nos. 50-413/86-25 and 50-414/86-27 Figures 2 through 6 2. cc w/encls: R. L. Dick, Vice President -Construction J. W. Hampton, Station Manager bcc w/encls: (See page 2) 8608110393 860804 PDR ADOCK 05000413 PDR

bcc w/encl:
T. Rehm, EDO
J. Callan, IE
K. N. Jabbour, NRR
NRC Resident Inspector
Document Control Desk
State of South Carolina

HCMristensen:aw

BWilson 07 /86 CAJulian Vulanted AFGibson 07/ /86 7/31/86 08/1/86

VLBrownlee

OH 186

3-1-8

Glenkins 07X 786 7/31-1

RWalker 071 /86