

APPENDIX A

NOTICE OF VIOLATION

Henry Souther Laboratories
Bloomfield, Connecticut 06002

Docket No. 030-22071
License No. 06-20785-01

As a result of the inspection conducted on August 27, 1986, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. Condition 14.A of License No. 06-20785-01 requires that sealed sources be tested for leakage at intervals not to exceed six months.

Contrary to the above, on August 27, 1986, a portable gauge containing 9 millicuries of cesium-137 and 44 millicuries of americium-241 was last leak tested on November 11, 1985.

This is a Severity Level IV violation. (Supplement VI)

- B. Condition 17 of License No. 06-20785-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in an application received on July 15, 1985 and a letter dated December 30, 1985.

The letter dated December 30, 1985, lists Mr. Thomas B. Kelly as the Radiation Safety Officer.

Contrary to the above, as of August 27, 1986, Mr. Robert Beauchesne was performing the duties of Radiation Safety Officer.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Henry Souther Laboratories is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8609220057 860916
REG1 LIC30
06-20785-01 PDR