

REVISED COPY OF MARCH REPORT

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH March, 1986

DOCKET NO. 50-250
UNIT NAME Turkey Point
DATE May 15, 1986
COMPLETED BY N. W. Grant
TELEPHONE 305/552-3675

Unit #3

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
04	860305	F	646.2	A	I	250-86-009	WG	ZZZZZZ	Unit 3 shut down to resolve potential concerns with the component cooling water (CCW) system which arose during a FPL initiated in depth review of select plant systems. Following testing and flow balancing of the CCW system and investigation and evaluation of potential concerns with diesel generator loading, the unit prepared to commence heat up to support returning to power operation in early April.

¹
F - Forced
S - Scheduled

²
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)
4- CONTINUED
5- LOAD REDUCTION

⁴
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

⁵
Exhibit I - Same Source

(9/77)

8607220035 860515
PDR ADOCK 05000250
PDR