

DMB COPY

AUG 19 1988

The Toledo Hospital
ATTN: William Jeffries, M.D.
Radiation Safety Officer
2142 North Cove Boulevard
Toledo, OH 43606

License No. 34-01710-05

Gentlemen:


This refers to the special safety inspection conducted by Mr. Robert E. Burgin of this office on July 15, 1988, of activities authorized by NRC Byproduct Material License No. 34-01710-05 and to the discussion of our findings with members of your staff at the conclusion of the inspection.

This special inspection was initiated by your July 11, 1988 telephonic notification to this office of a brachytherapy misadministration. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

Enclosure: Inspection Report
No. 030-02685/88001(DRSS)

cc w/enclosure:
DCS/RSB (RIDS)

RIII *REB*
Burgin/bt
8/18/88

YES ~
RIII *DW*
Wiedeman
8/18/88

8808290232 880819
REG3 LIC30
34-01710-05 PDC

IE07
11