## SAFETY INSPECTION

1. LICENSEE  1/ortheast Etalical Testing In 48 North Plains Industria Row Vallingford, Connecticut 06792  3. DOCKET NUMBER(S)  4. LICENSE NUMBER(S)	631 Park Avenue Region I King of Prussia Po 19406
030-17758 06-199	480 -01 June 20, 1986
Licensee:	
and representative records, interviews, with personnel, and observations by the	our license. The inspection consisted of selective examinations of procedures
1. Within the scope of this inspection, no violations were observed.	
2. The inspector also verified the steps you have taken to correct the viol those actions at this time.  3. During this inspection certain of your activities, as checked below, were THIS IS A NOTICE OF VIOLATION which is required to be posted in	
of a	
010	. 10 01 11 20120101, 101, 101, 101 01 04.42.
B. Containers located in	were not properly
labeled to indicate the presence of radioactive material. 10 CFR 20	0.203(f)(1), or (f)(2).
Пс	of sealed sources were not performed at the proper
frequencies. 10 CFR	License Condition Number
D. Records of	were not properly maintained.
10 CFR	or License Condition Number
E. Documents were not properly posted or otherwise made available.	10 CFR 19.11.
F. Reports or notifications of	were not made in accordance
with 10 CFR	
Н	
8701150352 860620 REG1 LIC30 06-19480-01 PDR	
	RETURN ORIGINAL TO
DESIGNATED ORIGINAL	REGION I
Certified By: WWW.	1E:07
I hereby state that within 30 days the actions described by me to the inspect. This statement of corrective actions is made in accordance with the requirement the NRC.	will be taken to correct the violations identified in the items checked above, ents of 10 CFR 2.201. No further response will be submitted unless required by
SIGNATURE - LICENSEE DATE	SIGNATURE - NRC INSPECTOR DATE