

0m0

SEP 1 1 1986

Docket No. 50-454

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. M. Hinds Jr., P. G. Brochman, and Ms. J. A. Malloy of this office on August 1 - September 2, 1986, of activities at Byron Station Unit 1, authorized by NRC Operating License No. NPF-37 and to the discussion of our findings with Mr. R. E. Querio and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by R. F. Warnick"

R. F. Warnick, Chief,
Reactor Projects Branch 1

Enclosure: Inspection Report
No. 50-454/86028(DRP)

See Attached Distribution

RIII
WZ
Hinds/jp

RIII
WZ
Lerch

RIII
WZ
Forney

RIII
RFW
Warnick
9/10/86

1E01
111

8609170434 860911
PDR ADOCK 05000454
Q PDR

Distribution

cc w/enclosure:

D. L. Farrar, Director
of Nuclear Licensing

V. I. Schlosser, Project Manager
Gunner Sorensen, Site Project
Superintendent

R. E. Querio, Plant Manager
DCS/RSB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII Braidwood
Phyllis Dunton, Attorney General's
Office, Environmental Control
Division

D. W. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE

Steve Lewis, ELD

L. Olshan, NRR LPM

H. S. Taylor, Quality Assurance
Division

TSS, RIII