JAN 1 2 1987

Georgia Power Company ATTN: Mr. J. H. Miller, Jr. President P. O. Box 4545 Atlanta, GA 30302

Gentlemen:

SUBJECT: CONFIRMATION OF ENFORCEMENT CONFERENCE - HATCH - DOCKET NOS. 50-321 AND 50-366

This confirms the conversation between Mr. H. C. Nix of your staff, and Mr. F. S. Cantrell of my staff, on December 30, 1986, concerning an enforcement conference to be conducted at the NRC Region II Office on January 22, 1987, at 9:00 a.m. We requested this meeting to discuss the design and procedural problems associated with the loss of water from the spent fuel pools in early December. Enclosed is a proposed meeting agenda identifying specific issues of concern.

Should you have any questions regarding these arrangements, we will be pleased to discuss them.

Sincerely, Original signed by/ M. L. Ernst/for

J. Nelson Grace Regional Administrator

| Enclosure:<br>Proposed Meet   | ing Agenda  |  |  |
|---|---|--|--|
| Nuclear Ope<br>J. T. Beckham<br>H. C. Nix, Si<br>Manager<br>A. Fraser, Ac | , Vice Preside<br>te Operations<br>ting Site QA S<br>ager, Nuclear<br>ng<br>Inspector<br>n, Executive S<br>rol Desk | ent, Plant Hat<br>General<br>upervisor<br>Safety | ch<br>8702090323 870112<br>PDR ADOCK 05000366<br>P PDR |
| RII<br>RCroteau:dm<br>01/5/87   | RII<br>FCantrell<br>01/5/87   | RII<br>VBrownlee<br>01/5 /87                     | RII<br>BWalker MErnst<br>01/5 /87 01/7 /87             |

IE45

## ENCLOSURE

## PROPOSED MEETING AGENDA

Georgia Power Company

January 22, 1987, 9:00 a.m.

- I. Opening Remarks
- II. Issues of Concern
  - A. The apparent failure to establish adequate design measures to ensure that the seals in the transfer canal were capable of preventing a significant loss of contaminated fuel pool water.
  - B. The apparent failure to follow procedures, lack of adequate procedures, and operation of safety-related equipment without a procedure.
  - C. The apparent failure of the failed seals to provide secondary containment integrity with respect to leakage of water to the environment.
  - D. The possible lack of management controls in this area which contributed to the event.

III. Closing Remarks

NRC

NRC