



Log # TXX-6266  
File # 10110  
909.2  
Ref # 10CFR50.55(e)

William G. Council  
Executive Vice President

February 6, 1987

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445 AND 50-446  
COMPONENT COOLING WATER PUMP  
IMPELLER LINEAR INDICATIONS  
SDAR: CP-86-11 (INTERIM REPORT)

Gentlemen:

On June 23, 1986, we notified you by our letter logged TXX-4871 of a deficiency involving the linear indication on impellers for the Component Cooling Water (CCW) pumps which we deemed reportable under the provisions of 10CFR50.55(e). This is an interim report submitted to status corrective action implemented to date. Our last interim report was logged TXX-6137, dated December 5, 1986.

Inspection and repair of the Unit 1, Train A, CCW pump impeller has been completed.

Due to construction rework involving an outage of all Unit 1, Train A, 6.9 kV switchgear, inspection of the Unit 1, Train B, CCW pump impeller has been deferred until after June 23, 1987.

Vendor repair of the replacement "spare" impeller is continuing. We will submit our next report no later than September 4, 1987.

Very truly yours,

W. G. Council

8702100345 870206  
PDR ADOCK 05000445  
S PDR

By:

  
G. S. Keeley  
Manager, Nuclear Licensing

GLB:lw

c - Mr. E. H. Johnson, Region IV  
Mr. D. L. Kelley, RI - Region IV  
Mr. H. S. Phillips, RI - Region IV

IE27  
110