

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Clay C. Warren
Chief Operating Officer

August 5, 1997

WO 97-0072

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555

Subject: Docket No. 50-482: Licensee Event Report 96-001-01

Gentlemen:

The attached revision to Licensee Event Report 96-001-00 is being submitted pursuant to 10 CFR 50.73 (a)(2)(iv) concerning an Engineered Safety Features actuation and 10 CFR 50.73 (a)(2)(i)(B) for a violation of Technical Specifications. Both incidents are part of the same event and are therefore being documented in one report. A revision is necessary because subsequent investigation and analysis on the icing at the Circulating Water Screenhouse have concluded that the root cause was different than initially reported.

If you should have any questions regarding this submittal, please contact me at (316) 364-8831 extension 4485, or Richard L. Flannigan at extension 4500.

Very truly yours,

Clay C. Warren
Clay C. Warren

CCW/jad

Attachment

cc: W. D. Johnson (NRC), w/a
E. W. Merschoff (NRC), w/a
J. F. Ringwald (NRC), w/a
J. C. Stone (NRC), w/a

IE22%

9708190266 970805
PDR ADOCK 05000482
S PDR

