

**PHILADELPHIA ELECTRIC COMPANY**

2301 MARKET STREET  
P.O. BOX 8699  
PHILADELPHIA, PA. 19101  
(215) 841-4000

April 14, 1986

Docket Nos. 50-277  
50-352

Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUBJECT: Delayed Submittal of Two Licensee Event Reports

Dear Dr. Murley:

On March 12, 1986, two Licensee Event Reports were discovered as not having been mailed to the Document Control Desk in a timely manner. The purpose of this letter is to provide an explanation of this incident which was immediately reported to the Resident Site Inspectors of each plant upon discovery. The reports of concern are:

Peach Bottom Atomic Power Station  
Docket No. 50-277  
LER 2-86-04, February 24, 1986

Limerick Generating Station  
Docket No. 50-352  
LER 86-009, February 26, 1986

The Licensing Section discovered this error by means of internal procedures which have been in use since 1981. The subsequent search found the two original reports, which had been misplaced in a "to be copied" bin. The reports were immediately telecopied to the Resident Site Inspectors and mailed to the Document Control Desk. The reports were also telecopied to the Region I Office to minimize effects of the delay.

8605020327 860414  
PDR ADOCK 05000277  
S PDR

1/0 1E22

Dr. Thomas E. Murley

April 14, 1986  
Page 2

A change has been made to the process of distributing correspondence to prevent this problem from recurring. The original signed reports will now be mailed immediately after a single copy is produced for the remaining distribution copies.

We regret any inconvenience these delayed submittals may have caused.

Very truly yours,



G. M. Leitch  
Superintendent  
Nuclear Generation Division

cc: E. M. Kelly, Senior Resident Site Inspector (LGS)  
T. P. Johnson, Resident Site Inspector (PBAPS)