

UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

AUG 2 7 1997

Charles M. Dugger, Vice President Operations - Waterford 3 Entergy Operations, Inc. P.O. Box 3 Killona, Louisiana 70066

SUBJECT: NRC INSPECTION REPORT 50-382/97-14 AND NOTICE OF VIOLATION


Dear Mr. Dugger:

An NRC inspection was conducted July 7-25, 1997, at your Waterford Steam Electric Station, Unit 3 reactor facility. Following the exit meeting the results of this inspection were discussed with Messrs. A. Wrape and E. Ewing of your staff on August 27, 1997. The enclosed report presents the scope and results of the inspection.

This inspection involved followup of nine open items including three violations and two unresolved items. Your staff had "ken adequate corrective action for two of the violations. However, we are concerned that your staff did not carefully review your existing license basis before reperforming the safety evaluation for changing your commitment to ANSI N195, "Fuel Oil Systems for Emergency Diesel Generators."

Both unresolved items were determined to be violations of NRC requirements. The circumstances surrounding both violations are described in detail in the enclosed report. The first violation involved failure to meet the load shed and sequence verification requirements of Technical Specification 4.8.1.1.2.e during Refueling Outage 7 for loads supplied via electrical contactors. In NRC Inspection Report 50-382/97-10, you were previously cited for a violation of Technical Specification 4.8.1.1.2.e. While we noted that you had not yet responded to this violation at the time of the exit, your staff had already taken corrective actions to address the violation, including this additional example, during Refueling Outage 8. Further, your subsequent response to the violation identified in NRC Inspection Report 50-382/97-10 described the corrective actions applicable to this additional violation example. Therefore, we have concluded that a further citation is not necessary. The second violation involved three failures to update your license basis as required by 10 CFR 50.71(e). We noted that your staff promptly initiated license document change requests to correct two of the examples and that you had previously docketed your corrective action commitments for the third example. While this violation is cited in the enclosed Notice of Violation (Notice), we have determined that these actions satisfy the intent of 10 CFR 2.201 and therefore, no further response is required.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, and its enclosure will be placed in the NRC Public Document Room (PDR).





Should you have any questions concerning this inspection, we will be pleased to discuss

Sincerely,

Arthur T. Howell III, Director Division of Reactor Safety

Docket No.: 50-382 License No.: NPF-38

## Enclosures:

- 1. Notice of Violation
- 2. NRC Inspection Report 50-382/97-14

cc w/enclosures: Executive Vice President and Chief Operating Officer Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39285-1995

Vice President, Operations Support Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway P.O. Box 651 Jackson, Mississippi 39205

General Manager, Plant Operations Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Manager - Licensing Manager Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Director, Nuclear Safety & Regulatory Affairs Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

William H. Spell, Administrator Louisiana Radiation Protection Division P.O. Box 82135 Baton Rouge, Louisiana 70884-2135

Parish President St. Charles Parish P.O. Box 302 Hahnville, Louisiana 70057

Mr. William A. Cross Bethesda Licensing Office 3 Metro Center Suite 610 Bethesda, Maryland 20814

Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502

E-Mail report to T. Freye (TJF) E-Mail report to NRR Event Tracking System (IPAS) E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IEO1)

bcc distrib. by RIV:

Regional Administrator **DRP** Director Branch Chief (DRP/D) Project Engineer (DRP/D) Branch Chief (DRP/TSS)

Resident Inspector DRS-PSB MIS System RIV File

DOCUMENT NAME: R:\\_W'AT\WT714RP.LJS

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RI:EB	C:EB	E	D:DRP	D:DRS 901	
LJSmith/lmb⊀	CAVanDenburgh		TPGwyn	ATHowellill	
07/29/97	08/4/97	for	08/1497	08/1970	

\*Previously concurred OFFICIAL RECORD COPY

E-Mail report to T. Freye (TJF)
E-Mail report to NRR Event Tracking System (IPAS)
E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IEO1)

bcc distrib. by RIV:

Regional Advinistrator DRP Director Branch Chief (DRP/D) Project Engineer (DRP/D) Branch Chief (DRP/TSS)

Resident Inspector DRS-PSB MIS System RIV File

## DOCUMENT NAME: R:\ WAT\WT714RP.LJS

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RI:EB	C:EB	E	D:DRP	D:DRS 9	
LJSmith/Imb€	CAVanDenburgh		TPGwyn	ATHowellill	
07/29/97	08/12/97	for	08/1497	08/197	
*Previously concu	Name and Address of the Owner, where the Owner, which is the O	4	L RECORD COP	6/	