

FEB 6 1987

Docket No. 50-341

The Detroit Edison Company
ATTN: B. Ralph Sylvia
Group Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the special safety inspection conducted by Messrs. D. S. Butler, and M. P. Huber of this office from January 12-15, 1987, of activities at Fermi 2, authorized by NRC Operating License No. NPF-43 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed By C. W. Hehl

Charles W. Hehl, Chief
Operations Branch

Enclosure: Inspection Report
No. 50-341/87003(DRS)

See Attached Distribution

^{YES}
RIII
MPH
Huber/lc

^{yes}
RIII
DAB
Butler

^{yes}
RIII
CWH for
Phillips

RIII
Wright
Hehl

8702170561 870206
PDR ADCK 05000341
Q PDR

11
IE 01

cc w/enclosure:

F. H. Sondgeroth, Licensing
Engineer

P. A. Marquardt, Corporate
Legal Department

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan
Public Service Commission

Harry H. Voight, Esq.

Nuclear Facilities and
Environmental Monitoring
Section

Monroe County Office of
Civil Preparedness