and from the

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H E MORGAN

January 12, 1987

REGION VISE

MECEIVED

TELEPHONE

(714) 368-6241

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention:

Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject:

Docket Nos. 50-361 and 50-362

Follow-up Report, Inoperable Fire Doors - December 1986 San Onofre Nuclear Generating Station, Units 2 and 3

Reference:

Letter, H. E. Morgan (SCE) to J. B. Martin (NRC),

dated December 15, 1986

In accordance with our referenced letter, this submittal provides the follow-up report of Technical Specification fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in December 1986.

Fire doors found inoperable during the December routine surveillances are identified in the Attachment and include: 5 latching mechanism failures, 3 closure mechanism failures. No doors were found blocked open in December. As each of these deficiencies was identified, compensatory fire watches, pursuant to Technical Specification 3.7.9, Action Statement 'a', were established. Door mechanism failures are being corrected on an "as found" basis.

8702170711 870112 PDR ADDCK 05000361 F 5 PDR

IL TE-OI

This monthly follow-up report and those sent previously provide updated information associated with an ongoing condition initially reported in 1983. The follow-up report covering inoperable fire doors identified in January 1987 will be submitted by February 16, 1987.

If you require any additional information, please so advise.

Sincerely,

45morg-

Enclosure:

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

U. S. Nuclear Regulatory Commission Document Control Desk

Institute of Nuclear Power Operations (INPO)

ATTACHMENT SOUTHERN CALIFORNIA EDISON COMPANY INOPERABLE FIRE DOORS FOR THE MONTH OF DECEMBER 1986 SAN ONOFRE NUCLEAR GENERATING STATION UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 5, as follows:

Door Number	Inoperable	Operable
AR-509 FH2-103 AR-502 AC-239 AC-417	11/16/86 11/16/86 11/16/86 12/02/86 12/09/86	12/02/86 12/31/86 12/04/86

II. Closure Mechanism Failures:

Number of doors inoperable - 3, as follows:

Door Number	Inoperable	Operable
AR-301 AR-301	12/02/86 12/13/86	12/06/86 12/14/86
AC-417	12/28/86	12/31/86

III. Doors Blocked Open:

Number of doors blocked open - None