

Commonwealth Edison Company
Byron Generating Station
4450 North German Church Road
Byron, IL 61010-9794
Tel 815-234-5441

August 12, 1999

ComEd

LTR: BYRON 99-0117
FILE: 3.03.0800

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Byron Station Unit 1
Facility Operating License No. NPF-37
NRC Docket Number STN 50-454


Subject: Information regarding Supplement to Licensee Event Report (LER)
98-008.

Reference: Letter from K. L. Kofron (ComEd) to Document Control Desk, Licensee
Event Report 98-008, dated April 3, 1998.

In the referenced letter, Byron Station transmitted Licensee Event Report 98-008, "Manual Reactor Trip Due to Loss of Communication During Rod Drop Testing Caused by Procedure Deficiency" to the NRC. In this report, we indicated that a supplemental report would be issued. However, Byron Station has now determined that a supplemental report to the subject LER is not warranted. No additional information was generated following the completion of Root Cause Investigation or following the completion of the corrective actions stated in the original LER.

Please direct any comments that you may have to Mr. Brad Adams, Regulatory Assurance Manager, at (815) 234-5441, extension 2280.

Respectfully,



William Levis
Site Vice President
Byron Station

WL/JD/dpk

cc: Regional Administrator - NRC Region
NRC Senior Resident Inspector - Byron Station

9908190091 990812
PDR ADOCK 05000454
S PDR

p:\99byltrs\990117.doc

IE2210