

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

September 30, 1986


Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555  
ATTENTION: Mr. B.J. Youngblood, Director  
PWR Project Directorate No. 4

Subject: McGuire Nuclear Station, Unit 2  
Docket No. 50-370  
Reactor Building Integrated Leak Rate Test;  
Determination of As-found Leakage

Dear Mr. Denton:

Attached is an addendum to the Integrated Leak Rate Test (IRLT) Report which was transmitted by letter dated September 26, 1986. In addition to supplementing the IRLT Report, this addendum provides the results of an investigation which was performed as a result of Inspections 50-369/86-16 and 50-370/86-16 (reference letter, H.B. Tucker to J.N. Grace, September 4, 1986). If there are any questions, contact Duke through normal Licensing channels.

Very truly yours,



Hal B. Tucker

SAG/34/jgm

Attachment

xc: Dr. J. Nelson Grace, Regional Administrator  
U.S. Nuclear Regulatory Commission - Region II  
101 Marietta Street, Suite 2900  
Atlanta, Georgia 30323

Mr. W.T. Orders  
Senior Resident Inspector  
McGuire Nuclear Station

8610090058 860930  
PDR ADOCK 05000370  
P PDR

*Acc'd*