



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JAN 19 1984

MEMORANDUM FOR: All Palisades Regional Review Committee Members
FROM: W. D. Shafer, Chairman, RRC
SUBJECT: REGIONAL REVIEW COMMITTEE MEETING MINUTES

Enclosed for your review are the minutes of the January 3, 1984 RRC meeting. You will note that the minutes indicate any commitments made or assignments given to RRC members. Please review these minutes carefully and be prepared to report the status of any issue under your cognizance.

Keep in mind that member attendance is mandatory and the use of alternates should be limited. Also please schedule your work so it will not impact on the meeting time.

W. D. Shafer
W. D. Shafer, Chairman
RRC

8606020132 860516
PDR FOIA
MURPHY86-266 PDR

~~LER 83-73 - Fire Protection System~~

LER 83-74 - Valves Failed to Meet "As Found" Acceptance Criteria

Possible generic implications. The licensee made adjustments to blowdown rings which were not expected to affect the lift setting but which proved to affect the lift settings. The vendor (Dresser) recommendations for adjusting these rings is not clear because apparently there are two different types of rings that have to be set. T. Wambach stated that he took this LER to the people in the Mechanical Engineering Branch who were previously involved with Dresser valve settings. It is possible that some of these rings adjusted according to the vendor's recommendation could be affecting the valves operation. The LPM for this issue will get back to NRR if there are any adverse findings.

~~LER 83-75 - Failure to Complete Hourly Fire Tours~~

~~Equipment Failure~~

~~LER 83-76~~

~~Personnel error - licensee failed to conduct five tours during the month~~
 An updated LER will be sent revising the code which was incorrectly reported. The SRI is concerned with the number of times the licensee
~~is failing to conduct these tours. The RRC will watch this carefully.~~