

APPENDIX A

NOTICE OF VIOLATION

GPU Nuclear Corporation
Forked River, New Jersey 08731

Docket No. 50-219
License No. DPR-16

During an inspection conducted on April 14 - 18, 1986, the following violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the violation is set forth below:

Section XVI of Appendix B to 10 CFR 50 requires that non-conformances are identified and corrected promptly.

Contrary to the above, as of April 16, 1986 a non-conformance identified 18 months earlier in technical specification audit S-OC-84-19 has not been corrected promptly.

The non-conformance is a 5 foot long crack in the fire wall of the Turbine Building south stairwell.

This is a Severity Level V Violation. (Supplement 1)

Pursuant to the provisions of 10 CFR 2.201, GPU Nuclear Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8606030029 860527
PDR ADOCK 05000219
Q PDR