

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

TELEPHONE  
(704) 373-4531

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

February 12, 1987


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2  
Docket Nos. 50-370  
LER 370/87-02

Gentlemen:

On January 14, 1987 it was discovered that rod position verification surveillances were not performed every 4 hours following a January 13, 1987 inoperability of the Unit 2 Operator Aid Computer as required by Technical Specifications. Pursuant to 10CFR 50.73 Sections (a)(1) and (d), in accordance with Section (a)(2)(i)(B), Licensee Event Report 370/87-02 was to have been submitted by February 12, 1987. At this time, all concerns regarding the event are not yet resolved. The complete report will be submitted by February 19, 1987.

Very truly yours,



Hal B. Tucker

PBN/48/jgm

xc: Dr. J. Nelson Grace  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St. NW, Suite 2900  
Atlanta, Georgia 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, New York 10020

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

Mr. Darl Hood  
U.S. Nuclear Regulatory Comm.  
Office of Nuclear Reactor Reg.  
Washington, D.C. 20555

Mr. W.T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

B702190075 B70212  
PDR ADOCK 05000370  
S PDR

IE22  
1/0