



Carolina Power & Light Company

P. O. Box 165, New Hill, North Carolina 27562
May 29, 1986

FILE: SH N-2/18
Item 228

MQAH 86-114

Dr. J. N. Grace
U. S. Nuclear Regulatory Commission
Region II
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400
CONCRETE DRY PACK REPAIRS

Dear Dr. Grace:

This is to confirm the May 29, 1986 telephone conversation between Mr. K. V. Hate' (CP&L) and Mr. L. Mellen. Mr. Mellen was informed that the April 18, 1986 potentially reportable item, pertaining to the potential for concrete dry pack repairs to be structurally unsound, has been evaluated and is considered not to be reportable per the provisions of 10CFR50.55(e).

Thank you for your consideration in this matter.

Yours very truly,

N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

NJC/mt

cc: Mr. G. Maxwell
Mr. J. M. Taylor

8606110271 860529
PDR ADOCK 05000400
S PDR

1/0 IE27