



Log # TXX-6261
File # 10110
903.8
Ref # 10CFR50.55(e)

William G. Council
Executive Vice President

February 13, 1987

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
WELDED ATTACHMENTS TO EMBEDDED STRIP PLATES
SDAR: CP-86-44 (FINAL REPORT)

Gentlemen:

On June 5, 1986, we verbally notified your Mr. I. Barnes of a deficiency involving the design/construction requirements for minimum separation of welded attachments to embedded strip plates which were not properly reflected in inspection procedures. We have concluded that this deficiency is reportable under the provision of 10CFR50.55(e). Our last interim report was logged TXX-6035, dated October 20, 1986.

The scope of SDAR CP-86-04, "PROXIMITY PLACEMENT - RICHMOND INSERTS TO EMBEDDED PLATES" has been expanded to include the deficiency identified in SDAR CP-86-44, "WELDED ATTACHMENTS TO EMBEDDED STRIP PLATES". See TXX-6260 dated February 13, 1987, for the required information pertaining to SDAR CP-86-44. All subsequent reports of this issue, concerning the status of implementation of corrective actions under the provisions of 10CFR50.55(e), will be reported via SDAR CP-86-04.

Very truly yours,

W. G. Council

BSD/lw

c - Mr. E. H. Johnson, Region IV
Mr. D. L. Kelley, RI - Region IV
Mr. H. S. Phillips, RI - Region IV

8702200268 870213
PDR ADOCK 05000445
S PDR

IE27
10