

Northeast
Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

September 29, 1997

Docket No. 50-336
B16759

Re: 10 CFR 50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 97-030-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on August 30, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii).

The following is NNECO's commitment made within this letter.

B16759-01: As a result of this condition, large bore piping and tubing with partial penetration welds, on both Emergency Diesel Generators, will be reworked and restored to code acceptable full penetration welds prior to entering Mode 4 from the current outage.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY




J. A. Price

Director - Millstone Unit No. 2

cc: see page 2

9710070025 970929
PDR ADOCK 05000336
S PDR



Attachment: LER 97-030-00

cc: H. J. Miller, Region I Administrator
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
W. D. Travers, PhD, Director, Special Projects Office
P. F. McKee, Deputy Director of Licensing, Special Projects Office
W. D. Lanning, Deputy Director of Inspections, Special Projects Office