



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

Henry V. Oheim
General Manager - Technical Section

September 30, 1997
BECO Ltr. 2.97. 098

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed supplemental Licensee Event Report (LER) 97-011-01, "Service Water System Single Failure Vulnerability," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitments:

- Further evaluate the SSW system single failure analysis, and
- Submit a supplemental LER by December 1, 1997

Please do not hesitate to contact me if there are any questions regarding this report.


H.V. Oheim

JWK/dmc/9701101

Enclosure: LER 97-011-01

cc's: next page

9710070182 970930
PDR ADOCK 05000293
S PDR



11/11 DE22

Boston Edison Company

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

INPO Records
700 Galleria Parkway
Atlanta, GA 30339-5957

Yankee Atomic Electric Company
580 Main Street
Bolton, MA 01740
Attn: James J. Duffy
Vermont Yankee Licensing

Standard BECo LER Distribution