

Log # TXX-4941
File # 10110
908.3

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

July 29, 1986

WILLIAM G. COUNCIL
EXECUTIVE VICE PRESIDENT

Mr. Eric H. Johnson, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012


SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NOS. 50-445 AND 50-446
6.9KV SWITCHGEAR BREAKER JACK SHAFT WELD FAILURE
SDAR: CP-86-14 (INTERIM REPORT)

Dear Mr. Johnson:

On March 11, 1986, we verbally notified your Mr. T. F. Westerman of a deficiency involving a weld failure in a component of a Class 1E 6.9KV switchgear breaker. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e). We have submitted interim reports logged TXX-4758 and TXX-4803, dated April 10, 1986, and May 14, 1986, respectively.

We are continuing our evaluation and anticipate submitting our next report by October 21, 1986

Very truly yours,



W. G. Council

JCH/gj

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8608060222 860729
PDR ADOCK 05000445
S PDR

86-849