



November 17, 1986

Docket Nos. 030-12529
030-12889

License Nos. 18-17303-01
18-17303-02G

John E. Glenn, Ph.D., Chief
Nuclear Materials Safety Section B
Division of Radiation Safety and Safeguards
Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Dear Dr. Glenn:

This refers to your letter dated November 14, 1986, in response to our letter dated October 8, 1986.

In response to item A(1) we corrected air in-leakage around our effluent air sample filter connections by taping all tube to tube and tube to filter housing junctions. We then tested for leakage and observed no leakage in any of the hood effluent air sampling lines.

In response to item A(2) we have provided an estimated dose for all personnel working around by-product material during the period October 20, 1985 to November 20, 1985. The estimated dose for each person was calculated by averaging badge readings for a six month period starting before October 20, 1985 and extending after November 20, 1985.

Sincerely,

James W. Champlin
Radiation Safety Officer

8701290176 870120
REG1 LIC30
18-17303-01 PDR

jc
enclosure

Ventrex Laboratories, Inc.

217 Read Street Portland, ME USA 04103
(207) 773-7231 1-800-341-0463 TX 710 221 6452

20 NOV 1986

<u>Name</u>	<u>Estimated Exposure (rems)</u>
Legassie, E.	.000
Hatch, S.	.000
Johnson, T.	.000
Harkins, J.	.000
Lewis, C.	.000
Hatch, S. (F)	.002
Nickerson, Margaret	.000
Moriarty, D.	.000
Sirois, K.	.000
Keef, L.	.000
Walker, L.	.000
Colby, C.	.000
Small, M.	.000
Fraser, J.	.000
Arab, A.	.000
Abrahamson, J.	.000
Bertin, R.	.000
Day, G.	.000
Nickerson, Melissa	.000
Workman, M.	.000
Liller, A.	.000
McMackin, B.	.000
Faulkner, D.	.000
Bassett, L.	.007